

SCORPIO EASHOOK LANYARD RECALL

Recall of SCORPIO EASHOOK (L060BA00) lanyards, sold individually or as part of the KIT VIA FERRATA EASHOOK (K029DA00 and K029DA01), due to risk of carabiner gate malfunction. Immediately stop using the products affected by this recall.

NOVEMBER 15 2021 **CURRENT**



Product, technical information

Search

Affected products

The affected products are :

- SCORPIO EASHOOK L060BA00 lanyard, sold individually
- KIT VIA FERRATA EASHOOK: K029DA00 and K029DA01

Only lanyards manufactured and delivered since January 1, 2021, and bearing serial numbers between 21A 0000000 000 and 21I 9999999 999, are affected.

Product Malfunction

These products have a malfunction: in rare cases, the carabiner's gate stays open and no longer closes automatically. Using a carabiner with the gate open does not ensure the user's safety in the event of a fall.

Your lanyard is affected by this recall

If you have a SCORPIO EASHOOK lanyard affected by this recall, even if it is functioning normally, stop using it immediately and return it to our local after-sales service via our contact form. Your lanyard will be exchanged as soon as possible. Petzl will pay for the return shipping costs.

If you are in US or Canada, please find below more details on the American CPSC and Canadian Government websites :

- [CPSC recalls](#)
- [Healthy Canadians recalls](#)

Product, technical information

Search



Should I look at the serial number of my SCORPIO EASHOOK lanyard, or that of the carabiners?

You should look at the serial number of your lanyard, not that of the carabiners.

Which SCORPIO lanyards are affected by this recall?

All SCORPIO EASHOOK lanyards, L060BA00, sold individually or as part of the KIT VIA FERRATA EASHOOK (K029DA00 and K029DA01), with a lanyard serial number between 21A 0000000 000 and 211 9999999 999, are affected by this recall.



[Product, technical information](#)

[Search](#)

L060BA00 manufactured and delivered in 2021 with a lanyard serial number between 21A 0000000 000 and 21I 9999999 999

Not affected by this recall



SCORPIO VERTIGO lanyard



previous version of SCORPIO EASHOOK lanyard

What should I do if my lanyard is affected by this recall?

Immediately stop using your lanyard and contact your local after-sales service via our [contact form](#) for an exchange.

Has this defect caused any personal injury?

To date, we are not aware of any personal injury caused by this defect.

I bought a VIA FERRATA EASHOOK KIT; which serial number should I look at to know if my lanyard is

Product, technical information

Search

Subscribe to the newsletter

and stay connected to our news

Email*

Join the community!



@PETZL_OFFICIAL



PETZL



PETZL
PROFESSIONAL



PETZL SPORT



PETZL



PETZL



About Petzl

Petzl Foundation

Petzl Solutions

Legal notice

Policy on personal data processing and cookie management

Accessibility Declaration

Petzl contact USA

Petzl America
info@petzl.com
(+1) 801 926 1500

Press access

The activities depicted are inherently dangerous. All users must be trained and competent in the use of the equipment for these activities.